

INSTALLATION INSTRUCTION  
**160 Low Voltage LED Track Luminaires**  
HHT-160LED, LHT-160LED, JHT-160LED

WAC LIGHTING  
Responsible Lighting®

**CAUTION:**

Read all instructions before installing.  
Switch off power before installing or re-lamping.  
Do not attempt to energize anything other than a track light fixture.  
All installation shall be in accordance with NEC and all local codes.

**OVERVIEW:**

Fixtures are designed for use on on WAC "L", "H", "J" series track.  
They may also be used on other manufacturer's brand of track  
(consult factory for compatibility).

**LAMPING:**

1. Use dimmable MR16 LED lamp (included)
2. Insert lamp into the shade so the lamp pins protrude through the back.
3. Place pins in the socket holes and twist 1/4" to the right. The lamp should feel firmly seated.
4. Seat the lamp under the "V" spring of the gimbal ring.

**FIXTURE INSTALLATION**

1. Note the track has a groove running it's length to indicate polarity.
2. Note the arrow on the locking tab.
3. Insert adapter into track slot and rotate it 90°. The arrow should point to the grooved side of the track.
4. Make sure the locking tab seats in the track slot.
5. Removal is the reverse procedure. Track heads may be positioned anywhere along the track length.

